



EUCON 2022.12.1 Release Notes

for Avid S4/S6, S1, S3, Dock, Avid Control, and Artist Series Control Surfaces

EUCON 2022.12.1 is a compatibility and bug fix release for EuControl and S4/S6 Master Module software.

macOS Privacy Settings

On macOS 10.15 (“Catalina”) and later you will be prompted to add applications such as EuControl, MC_Client, and Pro Tools to the Privacy list in System Preferences. If so, follow the on-screen instructions to add them (if you do not, EuControl will not be able to communicate keyboard shortcuts within Soft Keys).

If you experience unexpected behavior with Soft Keys that include keyboard shortcuts after adding EUCON software to the Privacy list, try the following:

- 1 Open System Preferences (or System Settings in Ventura) and go to the Security & Privacy.
- 2 Go to the Privacy tab, then select Accessibility in the list to the left.
- 3 Remove all EUCON software from the Accessibility list to the right.
- 4 Add all EUCON software back to the Accessibility Privacy list.

What is Fixed in EUCON 2022.12.1

EuControl Software and Surfaces

- It was possible to end up with duplicate Soft Keys after importing an appset saved in an earlier version of EuControl (GWSW-16441)
- Dynamic Soft Key names (such as Memory Locations and Layouts) could fail to update correctly in the Soft Key Command Editor displays (GWSW-16440)

Avid Dock

- It was possible for the Wheel modes to stop functioning after focusing away from a DAW and then back (GWSW-16465)

Avid Control

- Avid Control and other surfaces could sometimes freeze (GWSW-16446)

Avid S4/S6

- Changing the Surface arrangement in Settings > Surface while a workstation was attached could result in data loss or impaired performance (GWSW-16363)